


*Note:*

The ultrasonic transducer can be replaced without removing the bumper trim.

To remove ultrasonic transducer (1), it is necessary to partially detach the rear underbody panelling.



Disconnect associated plug connection.

Expand catches (1) and remove ultrasonic transducer (2) in direction of arrow.